



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	-27/-28	TSN:	17,762.4	TSO:	3,185.3	W/O#:	9540
PCE:	51008	CSN:	24,777	CSO:	7,526	TSHS:	525.2

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	8D567	15,203	3,797
Disk, 2 <sup>nd</sup> Stg.	3013712	8E779	12,964	11,036
Disk, 3 <sup>rd</sup> Stg.	3011713	3168	24,476	524
Impeller	3013176	2D973	9,983	9,017
Disk, CT	3013411	A8151	13,823	2,177
PT Disk, 1 <sup>st</sup> Stg.	3026812	23B158	19,388	612

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	19200099	801.0
FUEL PUMP	025323-101-03	12376	1,032.5
FUEL CONTROL UNIT	2524440-7-6	A48557	693.2
START FLOW CONTROL	3019109	12047	1,400.5
OIL/FUEL HEATER	10552E	WA12161	592.0
COMP. BLEED VALVE	3100829-03	1A161	1,400.5

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.