

# Component Maintenance Status

Heliwest Services Pty Ltd.

05-Nov-20 Colin Kilmast

**A/C Reg No:** VH-XRI

**Type:** AH - BO105LS A-3 - Helicopter

**A/C Serial No:** 2041

**Owner:** HW Leasing

**Posted TSN:** 7147.4

**Posted LSN:** 24219

**Last Flight:** 05-Dec-18

**DoM:** 01-May-93

ATA: Lvl:	Part No:	Description:	Position:	Project:	Changed:	Serial No:	*®:	Current Life:				Life Remaining:			
								TSN:	TSO:	CSN:	CSO: DoM/FF:	TTR:	TTO/TTI:	TCR:	CTO/CTI:
01	001	CHARGE TIME	Charge Time	N/A		2041-CT		85.80		0		N/A	N/A	N/A	N/A
23	002	069-1025-04	Transceiver	N/A		P10248			25.00			N/A	N/A	N/A	N/A
24	002	EO TDE3814-02	Battery Installation	N/A		2041		954.30			15-Nov-11	N/A	N/A	N/A	N/A
24	002	EO TDE4381-01	Role Modifications	N/A		2041		794.60			25-Jul-12	N/A	N/A	N/A	N/A
24	003	DC4381-02	Track	N/A		2041		794.60			25-Jul-12	N/A	N/A	N/A	N/A
24	003	PC925MJT	Battery	N/A		0577S17180010 7		60.80			09-Feb-18	N/A	N/A	N/A	N/A Scrap in -270
24	003	DC4381-01	Aux Power Outlet and	N/A		2041		794.60			25-Jul-12	N/A	N/A	N/A	N/A
24	003	PC925MJT	Battery	N/A		0577S17180011 1		60.80			09-Feb-18	N/A	N/A	N/A	N/A Scrap in -270
25	001	MODIFICATIONS	Modifications	N/A		2041		7147.40		24219		N/A	N/A	N/A	N/A
25	002	453-6603	Emergency Locator Tr	N/A		05985					05-Dec-11	N/A	N/A	N/A	N/A
25	003	452-6499	Battery	N/A		355941-41					18-Dec-12	N/A	N/A	N/A	N/A Scrap in -688
26	002	103335	Fire Extinguisher	N/A		8279	®	66.80			05-Jul-17	N/A	N/A	N/A	N/A O/H in 313
29	001	105-450121	Hydraulic System	N/A		05-0020		3909.25		15514		N/A	N/A	N/A	N/A
34	001	4021541-391	Indicator	N/A		77060177			25.00			N/A	N/A	N/A	N/A
34	001	5035P2-P44	Indicator	N/A		23373			73.80			N/A	N/A	N/A	N/A
62	001	23081-002	Starter/Generator	Engine # 1		1190			616.00			N/A	384	N/A	N/A
62	001	23081-002	Starter/Generator	Engine # 2		197			318.90			N/A	681.1	N/A	N/A
62	001	117-13103.13	Hexagaonal	N/A		19930529-01		7147.40				252.6	N/A	N/A	N/A
62	001	117-13103.13	Hexagaonal	N/A		19930529-02		7147.40				252.6	N/A	N/A	N/A
62	001	105-15150	Blade Assembly	N/A		5179		5423.40	1292.60			N/A	N/A	N/A	N/A
62	001	105-15150	Blade Assembly	N/A		5486		5423.40	1292.60			N/A	N/A	N/A	N/A
62	001	105-15150	Blade Assembly	N/A		5815		5423.40	1292.60			N/A	N/A	N/A	N/A
62	001	105-15150	Blade Assembly	N/A		5898		5423.40	1292.60			N/A	N/A	N/A	N/A
62	001	105-31791	Blade Assembly	N/A	HP11842	17-Dec-19						N/A	N/A	N/A	N/A
62	001	105-31791	Blade Assembly	N/A	HP11842	17-Dec-19						N/A	N/A	N/A	N/A

er



***Due Date:***

\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_

) 09-Feb-20

) 09-Feb-20

} 18-Dec-18

} 14-Sep-21

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

# Component Maintenance Status

Heliwest Services Pty Ltd.

05-Nov-20 Colin Kilmaster

**A/C Reg No:** VH-XRI

**Type:** AH - BO105LS A-3 - Helicopter

**A/C Serial No:** 2041

**Owner:** HW Leasing

**Posted TSN:** 7147.4

**Posted LSN:** 24219

**Last Flight:** 05-Dec-18

**DoM:** 01-May-93

ATA: Lvl:	Part No:	Description:	Position:	Project:	Changed:	Serial No:	*®:	Current Life:				Life Remaining:			
								TSN:	TSO:	CSN:	CSO: DoM/FF:	TTR:	TTO/TTI:	TCR:	CTO/CTI:
62	001 4639 003 001	Gearbox	N/A			955		2855.40	2855.40		N/A	744.6	N/A	N/A	
62	001 4639 002 001	Gearbox	N/A			609		3261.60	3261.60		N/A	338.4	N/A	N/A	
62	001 105-101021.17	Bolt	N/A			20070505-04		2115.60			3884.4	N/A	N/A	N/A	
62	001 105-101021.17	Bolt	N/A			20070505-02		2115.60			3884.4	N/A	N/A	N/A	
62	001 105-101021.17	Bolt	N/A			20070505-03		2115.60			3884.4	N/A	N/A	N/A	
62	001 105-101021.17	Bolt	N/A			20070505-01		2115.60			3884.4	N/A	N/A	N/A	
62	001 105-500001V001	Landing Gear	N/A			2041			73.00		N/A	N/A	N/A	N/A	
62	001 105-317391	Head Assembly	N/A	HP11842	17-Dec-19						N/A	N/A	N/A	N/A	
62	002 105-317391.12	Bolt	N/A	HP11842	17-Dec-19						3900	N/A	25350	N/A	
62	002 105-317391.12	Bolt	N/A	HP11842	17-Dec-19						3900	N/A	25350	N/A	
62	002 105-317261	Strap Pack	N/A	HP11842	17-Dec-19						3900	N/A	25350	N/A	
62	001 105-141041	Head Assembly	N/A			015		6512.70	21206	02-Dec-85	N/A	N/A	N/A	N/A	
62	002 J17322-1	Strap Assembly	N/A			LK13121		1595.30	10094	22-Oct-10	N/A	N/A	14906	N/A	Scrap in 716
62	002 J17322-1	Strap Assembly	N/A			LK13122		1595.30	10094	22-Oct-10	N/A	N/A	14906	N/A	Scrap in 716
62	002 J17322-1	Strap Assembly	N/A			LK13137		1595.30	10094	22-Oct-10	N/A	N/A	14906	N/A	Scrap in 716
62	002 J17322-1	Strap Assembly	N/A			LK13134		1595.30	10094	22-Oct-10	N/A	N/A	14906	N/A	Scrap in 716
62	002 105-141041.22	Bolt, TT Outer	N/A			155		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-141041.22	Bolt, TT Outer	N/A			158		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-141041.22	Bolt, TT Outer	N/A			159		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-141041.22	Bolt, TT Outer	N/A			162		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-141041.23	Bolt, TT Inner	N/A			155		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-141041.23	Bolt, TT Inner	N/A			158		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-141041.23	Bolt, TT Inner	N/A			164		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-141041.23	Bolt, TT Inner	N/A			165		6512.70	21206		10287.3	N/A	87994	N/A	
62	002 105-142241.01	Nut	N/A			015-1		6512.70	21206		12387.3	N/A	101644	N/A	
62	002 105-142241.01	Nut	N/A			015-2		6512.70	21206		12387.3	N/A	101644	N/A	
62	002 105-142241.01	Nut	N/A			015-3		6512.70	21206		12387.3	N/A	101644	N/A	
62	002 105-142241.01	Nut	N/A			015-4		6512.70	21206		12387.3	N/A	101644	N/A	

er



**Due Date:**

---

i 22-Oct-22

i 22-Oct-22

i 22-Oct-22

i 22-Oct-22

---

# Component Maintenance Status

Heliwest Services Pty Ltd.

05-Nov-20 Colin Kilmaster

**A/C Reg No:** VH-XRI

**Type:** AH - BO105LS A-3 - Helicopter

**A/C Serial No:** 2041

**Owner:** HW Leasing

**Posted TSN:** 7147.4

**Posted LSN:** 24219

**Last Flight:** 05-Dec-18

**DoM:** 01-May-93

ATA: Lvl:	Part No:	Description:	Position:	Project:	Changed:	Serial No:	*®:	Current Life:			Life Remaining:				
								TSN:	TSO:	CSN:	CSO: DoM/FF:	TTR:	TTO/TTI:	TCR:	CTO/CTI:
62	002	105-457211.14	Spring	1.		20140124-01		530.10		938		1869.9	N/A	14562	N/A
62	002	105-457211.14	Spring	1.		20140124-02		530.10		938		1869.9	N/A	14562	N/A
62	002	105-457211.14	Spring	1.		20140124-03		530.10		938		1869.9	N/A	14562	N/A
62	002	105-457211.14	Spring	1.		20140124-04		530.10		938		1869.9	N/A	14562	N/A
62	002	105-457211.14	Spring	1.		20140124-05		530.10		938		1869.9	N/A	14562	N/A
62	002	105-457211.14	Spring	1.		20140124-06		530.10		938		1869.9	N/A	14562	N/A
62	002	105-456214.11	Spring	2.		17-201		1717.50		5477		682.5	N/A	10023	N/A
62	002	105-456214.11	Spring	2.		17-202		1717.50		5477		682.5	N/A	10023	N/A
62	002	105-456214.11	Spring	2.		17-203		1717.50		5477		682.5	N/A	10023	N/A
62	002	105-456214.11	Spring	2.		17-204		1717.50		5477		682.5	N/A	10023	N/A
62	002	105-456214.11	Spring	2.		17-205		1717.50		5477		682.5	N/A	10023	N/A
62	002	105-456214.11	Spring	2.		17-206		1717.50		5477		682.5	N/A	10023	N/A
62	002	AP05VC-032-01	Pump	N/A		AH63158		3909.25				N/A	N/A	N/A	N/A
62	002	AP05VC-032-01	Pump	N/A		AH63165		3909.25				N/A	N/A	N/A	N/A
62	001	4639 001 006	Gearbox	N/A		48		7147.40	3612.70			N/A	95.3	N/A	N/A
62	002	4639 202 011	Free-Wheel	LH		973			1254.10			N/A	545.9	N/A	N/A
62	002	4639 202 011	Free-Wheel	RH		3173			1254.10			N/A	545.9	N/A	N/A
62	002	4639 305 002	Pole	N/A		3137		4008.30				7391.7	N/A	N/A	N/A
62	002	117-41904	Swashplate	N/A		05-0157		6751.80	3612.70			N/A	N/A	N/A	N/A
62	002	105-86565	Landing Light	N/A		2041		7147.40		24219		N/A	N/A	N/A	N/A
62	002	105-807014-01	Air Conditioner	N/A		2041		7147.40		24219	01-May-93	N/A	N/A	N/A	N/A
62	002	105-821814	Pulse Chip Detector	N/A		2041		7147.40		24219	01-May-93	N/A	N/A	N/A	N/A
62	002	105-800224	Wire Strike Protecti	N/A		2041		7147.40		24219	01-May-93	N/A	N/A	N/A	N/A
62	002	105-80901	Main Rotor Blade Fol	N/A		2041		7147.40		24219		N/A	N/A	N/A	N/A
67	001	117-421271	Block Assembly	N/A		2041						N/A	N/A	N/A	N/A
67	001	117-421261	Support	N/A		136						N/A	N/A	N/A	N/A
72	001	6898600	Engine Assembly	Engine # 1	HP11842		03-Mar-20					N/A	N/A	N/A	N/A

er



***Due Date:***

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

!

[Redacted]

[Redacted]

\_\_\_\_\_

[Redacted]

[Redacted]

\_\_\_\_\_

[Redacted]

\_\_\_\_\_

# Component Maintenance Status

Heliwest Services Pty Ltd.

05-Nov-20 Colin Kilmaster

**A/C Reg No:** VH-XRI

**Type:** AH - BO105LS A-3 - Helicopter

**A/C Serial No:** 2041

**Owner:** HW Leasing

**Posted TSN:** 7147.4

**Posted LSN:** 24219

**Last Flight:** 05-Dec-18

**DoM:** 01-May-93

ATA: Lvl:	Part No:	Description:	Position:	Project:	Changed:	Serial No:	*®:	Current Life:				Life Remaining:			
								TSN:	TSO:	CSN:	CSO:	DoM/FF:	TTR:	TTO/TTI:	TCR:
72	002	23033192	Compressor Assembly	Engine # 1	HP11842	03-Mar-20						N/A	N/A	N/A	N/A
72	002	23035177	Gearbox Assembly	Engine # 1	HP11842	03-Mar-20						N/A	N/A	N/A	N/A
72	002	23033185	Turbine Assembly	Engine # 1	HP11842	03-Mar-20						N/A	N/K	N/A	N/A
72	003	23030975	Impeller Assembly	Engine # 1	HP11842	03-Mar-20						15000	N/K	25000	N/A
72	003	6895801	Wheel #1	Engine # 1	HP11842	03-Mar-20						1550	N/A	3000	N/A
72	003	23004223	Wheel #2	Engine # 1	HP11842	03-Mar-20						1550	N/A	3000	N/A
72	003	6899383	Wheel #3	Engine # 1	HP11842	03-Mar-20						4550	N/A	6000	N/A
72	003	6889054	Wheel #4	Engine # 1	HP11842	03-Mar-20						4550	N/A	6000	N/A
72	001	6898600	Engine Assembly	Engine # 2			CAE280015	6374.60		16129		N/A	N/A	N/A	N/A
72	002	23005280	Compressor Assembly	Engine # 2			CAC70772	6461.00		10147		N/A	N/A	N/A	N/A
72	002	23035177	Gearbox Assembly	Engine # 2			CAG28017	6374.60	602.70			N/A	N/A	N/A	N/A
72	002	23033190	Turbine Assembly	Engine # 2			CAT70748	3165.90	318.90	5144	297	N/A	1181.1	N/A	N/A
72	003	6899355	Impeller	Engine # 2			LP61091	6461.00	6461.00	10147		8539	3539	14853	N/A
72	003	6895801	Wheel #1	Engine # 2			X590619	318.90		297		1231.1	N/A	2703	N/A
72	003	23004223	Wheel #2	Engine # 2			X515987	318.90		297		1231.1	N/A	2703	N/A
72	003	6899383	Wheel #3	Engine # 2			HX91824	1166.30		2765		3383.7	N/A	3235	N/A
72	003	6889054	Wheel #4	Engine # 2			HX66173	1166.30		2765		3383.7	N/A	3235	N/A
72	003	23073565	Shield Assembly	Engine # 2			TBA	312.60	312.60	297	297	N/A	N/A	N/A	N/A
73	002	388100-5	Pump Assembly	Engine # 1	HP11842	03-Mar-20						N/A	N/K	N/A	N/A
73	002	2524738-37	Fuel Control Unit	Engine # 1	HP11842	03-Mar-20						N/A	N/K	N/A	N/A
73	002	2524677-12	Governor	Engine # 1	HP11842	03-Mar-20						N/A	N/K	N/A	N/A
73	002	M250-10604	Nozzle Assembly	Engine # 1	HP11842	03-Mar-20						N/A	N/K	N/A	N/A
73	002	6896822	EDFP	Engine # 2			T200318		318.90			N/A	2681.1	N/A	N/A
73	002	2524738-37	Fuel Control Unit	Engine # 2			330241		437.10			N/A	2062.9	N/A	N/A
73	002	23070100	Governor	Engine # 2			BR37731		318.90			N/A	1681.1	N/A	N/A
73	002	23077067	Fuel Nozzle	Engine # 2			1WF00544		1465.20			N/A	534.8	N/A	N/A
75	002	23074227	Bleed Valve	Engine # 1	HP11842	03-Mar-20						N/A	N/K	N/A	N/A

er



***Due Date:***

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]



# Component Maintenance Status

Heliwest Services Pty Ltd.

05-Nov-20 Colin Kilmast

**A/C Reg No:** VH-XRI      **Type:** AH - BO105LS A-3 - Helicopter      **A/C Serial No:** 2041      **Owner:** HW Leasing  
**Posted TSN:** 7147.4      **Posted LSN:** 24219      **Last Flight:** 05-Dec-18      **DoM:** 01-May-93

ATA: Lvl: Part No:	Description:	Position: Project:	Changed:	Serial No: *®:	Current Life:				Life Remaining:				
					TSN:	TSO:	CSN:	CSO: DoM/FF:	TTR:	TTO/TTI:	TCR:	CTO/CTI: Days Rem:	
75 002 23074227	Bleed Valve	Engine # 2		FF35940		997.20				N/A	502.8	N/A	N/A
79 002 STC SH3067SO	Oil Filter Installat	N/A		2041		7147.40				N/A	N/A	N/A	N/A

er



***Due Date:***

\_\_\_\_\_